

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

83 APR 13 AIO: 11

April 6, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 2
Docket No. 50-370

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-370/83-02. This report concerns T.S. 3.9.8.2, "Two independent Residual Heat Removal (RHR) Loops shall be operable, and at least one RHR loop shall be in operation." This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

H.B. Tucker / BTU

Hal B. Tucker

PBN:jfw
Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
Senior Resident Inspector-NRC
McGuire Nuclear Station

8304190432 830406
PDR ADOCK 05000370
S PDR

OFFICIAL COPY
1622