

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

April 11, 1983

BLRD-50-438/81-05
BLRD-50-439/81-06

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEfonte NUCLEAR PLANT UNITS 1 AND 2 - LAMBDA POWER MODULE FAILURES -
BLRD-50-438/81-05, BLRD-50-439/81-06 - ADDITIONAL SUPPLEMENTAL
INFORMATION

The subject deficiency was initially reported to NRC-OIE Inspector R. W. Wright on December 18, 1980 in accordance with 10 CFR 50.55(e) as NCR BLN EEB 8006. This was followed by our first interim report dated January 19, 1981, our final report dated July 21, 1981, our revised final report dated March 23, 1982, and our second revised final report dated June 17, 1982, and our supplemental report dated September 27, 1982.

As discussed with NRC-OIE Inspector Paul Fredrickson on April 4, 1983, the date of April 1, 1983 for completion of corrective actions indicated in our supplemental report on this matter was not met. The vendor has not completed the necessary corrections to the power supplies as required by previously discussed nonconformance 1952. Therefore, the modules cannot yet be installed to complete the corrective action as required by the subject nonconformance. The corrective action on this matter will be completed by September 1, 1983. We consider 10 CFR Part 21 applicable to this deficiency.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

8304190500 830411
PDR ADOCK 05000438
S PDR

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339