



Carolina Power & Light Company

P. O. Box 101, New Hill, North Carolina 27562
April 8, 1983

FILE: SH N-2/18
Item 120

MQAH 83-30

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1
DOCKET NO. 50-400
DEFICIENCIES IN CONTAINMENT BUILDING
STRUCTURAL STEEL MEMBERS

Dear Mr. O'Reilly:


This is to confirm the April 8, 1983 telephone conversation between Mr. N. J. Chiangi and Mr. C. Hehl. Mr. Hehl was informed that the March 14, 1983 potentially reportable item, pertaining to deficiencies discovered in two (2) structural members installed in the Containment Building, has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e) and 10CFR, Part 21.

Thank you for your consideration in this matter.

Yours very truly,

NJC/mt

cc: Mr. G. Maxwell
Mr. V. Stello


N. J. Chiangi - Manager
Quality Assurance/Quality Control
Harris Plant

8304190522 830408
PDR ADOCK 05000400
S PDR

OFFICIAL COPY

10 27