

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	6	7	7	0	3	0	7	8	3	8	U	4	0	6	8	3	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08 _____ 3

09		SYSTEM CODE ZZ		CAUSE CODE X		CAUSE SUBCODE Z		COMPONENT CODE ZZZZZZ						COMP. SUBCODE 19		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	SEQUENTIAL REPORT NO. 011		OCCURRENCE CODE 03		REPORT TYPE L		REVISION NO. 0	
17		LER/RO REPORT NUMBER 83		EVENT YEAR 83		SHUTDOWN METHOD Z		HOURS 000		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER Z999	
13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The repositioning of a valve in the line from the core support floor vent to the gas
1 1 waste system apparently caused too rapid of a flow increase to the gas waste system
1 2 for the vacuum tank pressure control system to react. The rupture disc was replaced,
1 3 and the system was returned to normal operation. No further corrective action is
1 4 anticipated or required.

FACILITY STATUS						% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
1	5	C	0	1	N/A		A	Operator Observation - Control Room	
7	8	9	10	11	12	13	14	15	

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 G (33) N (34) 0.52 $\mu\text{Ci/cc}$ of ^{138}Xe Gas Waste Vacuum Tank to Atmosphere

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	000	(37) Z	(38) N/A	(39)				

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		N/A	

8304190535 830406
PDR ADCK 05000267
S PDR

7		8		9		11		12			
				LOSS OF OR DAMAGE TO FACILITY							
		TYPE		DESCRIPTION							
1	9	Z	(42)	N/A						(43)	

7	8	9	10											80					
PUBLICITY				NRC USE ONLY															
ISSUED				DESCRIPTION															
20				N/A															

NAME OF PREPARER

PHONE: (303) 785-2224

R4 IE22
Docket 50-267

Date
Received: 4-8-83

Date of
Document: 4-6-83

Title: INCIDENT REPORT (50 Dkt) LER/RO/AO/ETC. P-83135 + LER 83-011

Document Control Desk Rids Code H005

(Region copy, NRC PDR, LPDR, NSIC, NTIS)

LTR. ENCL.

LTR. ENCL.

Region IV Internal:

Region IV Suspense Copy ✓

P. Wagner ✓

~~REDACTED~~

Original sent to DMB

Region IV External:

State: COLORADO ✓

REGION IV ROUTING:

J. Gagliardo ✓

J. Collins

P. Check

R. Bangart

G. Madsen

Section Chief

Do not return to RIV File Room

NRR OVERSIGHT:

NRR/ORB3/BC: R.A.CLARK ✓

NRR/ORB3/PM: C.TRAMMELL ✓

NRR/DIR/DL: D.EISENHUT ✓

NRR/DIR/DE: R.VOLLMER ✓

NRR/DIR/HFS: H.THOMPSON ✓

NRR/DIR/DSI: R.MATTSON ✓

NRR/DIR/DST: S.HANAUER ✓

NRR/

Copies Required 25

Copies Received 1

Encl. only

Letter only

*File Copy

Other

ACRS

10 ✓

JAMES HARD ✓

IE/DEQA/EAB ✓

IE/DRP/CVSPS ✓

AEOD ✓

~~REDACTED~~

* One copy distributed unless otherwise indicated ()

* Original file copy will be returned to RIV