



Entergy Operations, Inc.
River Bend Station
5485 U.S. Highway 61
PO. Box 220
St. Francisville, LA 70775
(504) 336-6225
FAX (504) 635-5068

JAMES J. FISICARO
Director
Nuclear Safety

October 7, 1994

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: River Bend Station - Unit 1
Docket No. 50-458
Sixth Fuel Cycle Core Operating Limits Report (COLR), Revision 1
File No.: G9.5, G9.25.1.5

RBFI-94-0067
RBG-40934

Gentlemen:

Enclosed is Revision 1 of the River Bend (RBS) Core Operating Limits Report (COLR) for the sixth fuel cycle. As a result of locating and removing the damaged fuel bundle minor changes to the loading configuration were necessary. This report is submitted in accordance with Technical Specification 6.9.3.4 of Appendix A to RBS Facility Operating License NPF-47. A change to the General Electric Supplemental reload licensing submittal was not necessary, the limits set in revision 0 of the COLR remain applicable.

For further information, contact Mr. G. H. Davant of my staff at (504) 336-6223.

Sincerely,

JJF/jr
enclosure

cc: U. S. Nuclear Regulatory Commission, Region IV
NRC Resident Inspector
Louisiana Department of Environmental Quality, Radiation Protection Division

9410130239 941007
PDR ADDCK 05000458
P PDR

ADD 1