

*Southern California Edison Company*

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

RECEIVED  
NRC

SCE

1983 APR 18 PM 12:53

REGION V LSS

TELEPHONE  
(414) 492-7700

H. B. RAY

STATION MANAGER

April 18, 1983

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator


Dear Sir:

Subject: Dockets No. 50-361 and 50-362  
30-Day Report  
Licensee Event Report No. 83-034 (Docket 50-361)  
San Onofre Nuclear Generating Station, Units 2 & 3

Pursuant to Sections 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-10 and NPF-15 for San Onofre Units 2 and 3, respectively, this submittal provides the required 30-day written report and a copy of Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.7.5 associated with the Control Room Emergency Air Cleanup System (CREACUS). A single LER for the occurrence for Unit 2 is provided in accordance with NUREG 0161, since the occurrence involved a system shared between Units 2 and 3. Enclosed LER 83-034 addresses the event, including corrective actions to prevent recurrence.

If there are any questions regarding this event, please contact me.

Sincerely,



Enclosure: LER 83-034, Units 2/3

8304220312 830418  
PDR ADDCK 05000361  
S PDR

IE-22  
83-173

J. B. Martin

-2-

April 18, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)

R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission  
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)