

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY

STATION MANAGER

April 14, 1983

RECEIVED
NRC

SCE

1983 APR 19 PM 12:56

RECEIVED

TELEPHONE
(714) 492-7700

Mr
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator


Dear Sir:

Subject: Docket Nos. 50-361 and 50-362
30-Day Report
Licensee Event Report No. 83-033 (Docket 50-361)
San Onofre Nuclear Generating Station, Units 2 & 3

Pursuant to Sections 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating Licensee NPF-10 and NPF-15 for San Onofre Units 2 and 3, respectively, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) for an occurrence involving Limiting Condition for Operation (LCO) 3.3.2 associated with the Toxic Gas Isolation System. Since this occurrence involves a shared system between Unit 2 and Unit 3, in accordance with NUREG 0161, a single LER for Unit 2 (Docket 50-361) is provided. Enclosed LER 83-033 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding the above, please contact me.

Sincerely,



Enclosure: LER 83-033 (Docket 50-361)

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control (MIPC)

Institute of Nuclear Power Operations (INPO)

8304220368 830414
PDR ADDCK 05000361
S PDR

IE-22
83-172