



- I. LER NUMBER: 82-180/03X-1
- II. LASALLE COUNTY STATION: Unit 1
- III. DOCKET NUMBER: 050-373/374
- IV. EVENT DESCRIPTION:

During review of Technical Specifications Table 3.7.9-2 it was discovered that several administrative/clerical errors existed. These errors resulted in the Technical Specification not reflecting the installation in some cases. The errors included: snubbers being assigned two different numbers and therefore listed twice, listing of restraints other than snubbers, listing of snubbers which had been deleted from the plant by approved design changes, omission of snubbers, and location errors.

V. PROBABLE CONSEQUENCES:

Although the Technical Specification did not reflect installation in all cases, installation was in accordance with plant design. The only discrepancy was in transposing design information into Technical Specification Tables. Since no violation of plant design occurred, the plant was maintained in a safe condition at all times.

VI. CAUSE:

Previous Technical Specification submittals were generated prior to incorporation of final linewalk information into the Architect Engineer's design documents. This information included design of small bore restraints by the site piping contractor. Therefore, due to the timing of Technical Specification submittal requirements, errors were generated in assembling the design information into a one for one table for Technical Specification 3.7.9-2.

VII. CORRECTIVE ACTION:

A revision of Technical Specification Table 3.7.9-2 is presently in the process of being submitted via onsite review 82-47 for the purpose of eliminating snubbers with small thermal movements. Correction of the aforementioned discrepancies will be included with this submittal.

Prepared by: Dale Spencer