

Docket No. 50-346

License No. NPF-3

Serial No. 1-343

April 6, 1983



RICHARD P. CROUSE  
Vice President  
Nuclear  
(419) 259-5221

Mr. C. E. Norelius, Director  
Division of Engineering & Technical Programs  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Norelius:

Toledo Edison received Inspection Report 83-01 (Log No. 1-747) dated March 8, 1983, pertaining to Davis-Besse Nuclear Power Station Unit 1 procedure adherence, drawing control, maintenance activities, and reporting requirements. These topics were also discussed during the March 8, 1983 enforcement conference conducted by you and members of your staff. Further discussion of Toledo Edison's corrective action program will occur at the follow-up meeting scheduled for the week of April 18, 1983. Following that meeting, Toledo Edison will submit a written report describing our corrective action program.

Since the corrective action program will contain the information required for our response to Inspection Report 83-01, I feel it is appropriate to delay the Inspection Report response to coincide with our corrective action program submittal.

Very truly yours,

RPC:RFP:lrh

cc: DB-1 NRC Resident Inspector

8304220492 830418  
PDR ADOCK 05000346  
PDR