



DUKE POWER

May 7, 1991

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 2
Docket No. 50-370
Unit 2 Outage 6, 1990 Inservice Inspection Report

Pursuant to 10CFR 50.55a and the ASME Code, please find attached the results of the McGuire 1990 refueling outage Inservice Inspections.

Very truly yours,

M. S. Tuckman
M. S. Tuckman

ltb\
Attachment
xc: (without attachment)

S. D. Ebnetter
Regional Administrator, Region II

T. A. Reed, ONRR

P. K. Van Doorn, McGuire
Senior Resident Inspector

AOA?
11