

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J O C P 1 2 0 0 - 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 CAT 36

CON'T 01 L G 0 5 0 0 0 2 1 9 7 0 3 1 4 8 3 8 0 4 1 1 2 8 3 9

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On March 1, 1983, during preventive maintenance on Core

03 Spray Booster Pump NZ03A breaker an incorrect UV trip coil was installed

04 which subsequently prevented a manual start. This event is

05 considered to be a reportable occurrence as defined in the Tech Spec,

06 paragraph 6.9.2.b.3. As plant configuration did not require the

07 Core Spray System to be operable and since the redundant Core Spray loop

08 was operable, if needed, the safety significance is considered minimal.

09 S F 11 A 17 X 13 R E L A Y X 14 D 15 Z 16

SYSTEM CODE 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP SUBCODE 19 VALVE SUBCODE 20

17 8 3 0 0 8 0 3 L 0

LER/RO REPORT NUMBER 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 28 29 REPORT TYPE 30 REVISION NO. 32

A X Z Z 0 0 0 0 Y N L G 0 8 0

ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 ATTACHMENT SUBMITTED 40 NPD-4 FORM 300 42 PRIME COMP. SUPPLIER 43 COMPONENT MANUFACTURER 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The cause was attributed to personnel error in delivering, certifying,

11 accepting, labling, storing, and installing the wrong part in the

12 subject breaker. Corrective Action was to replace the incorrect part

13 with the correct part. Vendor will be notified. Additional controls

14 will be evaluated.

15 H 28 0 0 0 29 NA A 31 Core Spray System Flush 32

FACILITY STATUS 7 8 9 % POWER 10 11 12 OTHER STATUS 13 14 METHOD OF DISCOVERY 44 45 46 DISCOVERY DESCRIPTION 47

16 Z 33 Z 34 NA NA NA

ACTIVITY CONTENT 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

RELEASED OF RELEASE 10 11 12 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

17 0 0 0 37 Z 38 NA

PERSONNEL EXPOSURES NUMBER 11 12 TYPE 13 14 DESCRIPTION 39

18 0 0 0 40 NA

PERSONNEL INJURIES NUMBER 11 12 DESCRIPTION 41

19 0 0 0 42 NA

LOSS OF OR DAMAGE TO FACILITY TYPE 11 12 DESCRIPTION 43

20 Z 44 NA

PUBLICITY ISSUED DESCRIPTION 45

21 N 46 NA

NAME OF PREPARER Denny B. Custodio PHONE. (609) 971-4892

NRC USE ONLY