



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 15, 1983

L. V. MAURIN

Vice President Nuclear Operations

W3I83-0121

Q-3-A35.07.63

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency Report No. 63
"Procurement of Spare/Replacement Parts"
Second Interim Report

REFERENCE: LP&L letter W3I82-0061 from L. V. Maurin to J. T. Collins
dated October 8, 1982

Dear Mr. Collins,

As of March 31, 1983 a total of 310 purchase orders for safety-related and/or quality-related spare and replacement parts were reviewed by an independent consultant and of these approximately 30 percent were found to be lacking sufficient documentation for use in safety-related applications. Additionally, this review has been expanded to include all purchase orders issued by LP&L for plant equipment and consumables prior to July 1, 1982. The review and identification of deficient items is presently scheduled for completion near the end of April and it is expected that the final resolution of all deficiency notices generated in this effort will require an additional two months to close out. A final report will, therefore, be transmitted to the NRC by July 29, 1983.

Very truly yours,

L. V. Maurin

IE-27

LVM/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8304250150 830415
PDR ADOCK 05000382
S PDR