

LICENSEE EVENT REPORT

UPDATE REPORT - PREVIOUS REPORT  
DATE 081882

CONTROL BLOCK: 1 2 3 4 5 6 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C T M N S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1

REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 Upon returning to 100% power on 19 July 1982, an unidentified leak in the Reactor

0 3 Coolant System in excess of 1 GPM was calculated. In accordance with T.S. 3.4.6.2,

0 4 Millstone 2 proceeded to cold shutdown, and a visual inspection revealed the follow-

0 5 ing valves to be leaking: 2-RC-403, 2-RC-405 and 2-RC-253. Similar LER's: 79-15

0 6 and 81-33.

0 7

0 8

7 8 9 80

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 VAL V E X 14 COMP. SUBCODE 15 VALVE SUBCODE 16

0 9

17 LER NO REPORT NUMBER 21 22 EVENT YEAR 8 2 23 24 SEQUENTIAL REPORT NO. 0 3 2 25 26 27 28 OCCURRENCE CODE 0 3 29 30 REPORT TYPE X 31 32 REVISION NO. 1

18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 38 ATTACHMENT SUBMITTED 41 NRPD-4 FORM SUB 42 PRIME COMP. SUPPLIER 43 COMPONENT MANUFACTURER 44 45 46 47

18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

A 18 Z 19 A 20 A 21 0 3 1 0 22 Y 23 N 24 A 25 V 0 8 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The seal ring was replaced on valve 2-RC-403. The packing was adjusted on valve

1 1 2-RC-405 and the packing was replaced on valve 2-RC-253.

1 2

1 3

1 4

7 8 9 80

FACILITY STATUS 7 8 9 10 % POWER 11 12 13 OTHER STATUS 30 METHOD OF DISCOVERY 44 45 46 DISCOVERY DESCRIPTION 32

1 5 E 28 1 0 0 29 NA A 31 Leakage calculated

ACTIVITY CONTENT 7 8 9 10 RELEASED OF RELEASE 11 12 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

1 6 Z 33 Z 34 NA

PERSONNEL EXPOSURES 7 8 9 10 NUMBER 11 12 TYPE 13 DESCRIPTION 39

1 7 0 0 0 37 38 NA

PERSONNEL INJURIES 7 8 9 10 NUMBER 11 12 DESCRIPTION 41

1 8 0 0 0 40 NA

LOSS OF OR DAMAGE TO FACILITY 7 8 9 10 TYPE 11 12 DESCRIPTION 43

1 9 Z 42 NA

PUBLICITY 7 8 9 10 ISSUED 11 12 DESCRIPTION 45

2 0 N 44

8304280314 830421  
PDR ADOCK 05000336  
S PDR

NAME OF PREPARER Robert Borchert

PHONE (203) 447-1791 X-4418

NRC USE ONLY

68 69 80-917-926