



Wisconsin Electric POWER COMPANY
231 W. MICHIGAN, P.O. BOX 2046, MILWAUKEE, WI 53201

April 25, 1983

Mr. J. G. Keppler, Regional Administrator
Office of Inspection and Enforcement,
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NO. 50-266
LICENSEE EVENT REPORT NO. 82-022/01X-2
POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report No. 82-022/01X-2 (a revised report) with an attachment which provides a description of an event reportable in accordance with Technical Specification 15.6.9.2.A.3, "Abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment."

This report is an update of information previously provided with Licensee Event Report No. 82-022/01X-1, dated December 9, 1982. The additional information provided with this update is contained in the attachment to the LER and is identified by a margin bar.

Very truly yours,

Vice President-Nuclear Power

C. W. Fay

Enclosure

Copy to NRC Resident Inspector

IE22