



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2991 • BEAUMONT, TEXAS 77704


AREA CODE 713 838-6631

April 25, 1983
RBG-14,866
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-72



IF-27

On August 30, 1982, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning the improper installation (torquing), testing, and inspection of concrete drilled-in-expansion-type anchors (DR-72). GSU's evaluation has not been completed. GSU is awaiting additional information from our architect-engineer. An interim or final status report will be provided by June 10, 1983.

Sincerely,

William J. Bocker
for J. E. Bocker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB
JEB/RJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)