

CONTROL BLOCK:

						1
--	--	--	--	--	--	---

 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

C 1		C O F S V I 1 2 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 2 0 4 L 5											
7 8		9 14 15 25 26 30 57 CAT 58											
CON'T		REPORT SOURCE		L 6 0 5 0 0 0 2 6 7 7 0 3 3 1 8 3 8 0 4 2 8 8 3 9									
7 8		60 61		DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80									
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)													
0 2		On March 31, 1983, two Class 1 hydraulic shock suppressors were found inoperable.											
0 3		This constitutes operation in a degraded mode of LCU 4.3.10 and is reportable per											
0 4		Fort St. Vrain Technical Specification AC 7.5.2(b)2. No accompanying occurrence. No											
0 5		affect on public health or safety. Similar reports are RO's: 82-001, 82-008, 82-016,											
0 6		82-032, 82-037, 82-052, and 83-004.											
0 7													
0 8													
7 8 9													
0 9		SYSTEM CODE H B 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE S U P O R T 14 COMP. SUBCODE D 15 VALVE SUBCODE Z 16 LER/RO REPORT NUMBER 17 EVENT YEAR 8 3 21 SEQUENTIAL REPORT NO. 0 1 6 24 OCCURRENCE CODE 0 3 28 REPORT TYPE L 30 REVISION NO. 0 32 ACTION TAKEN E 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER I 2 0 7 26											
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)													
1 0		Thermal pipe movement caused the snubbers to become fully extended. One snubber was											
1 1		disconnected, and the stanchion length adjusted. The second snubber was replaced with											
1 2		a qualified spare, and stanchion length adjusted. No further corrective action is											
1 3		anticipated or required.											
1 4													
7 8 9													
1 5		FACILITY STATUS G 28 % POWER 0 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 Personnel Observation 32											
1 6		ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 N/A 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE 36											
1 7		PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 N/A 39											
1 8		PERSONNEL INJURIES NUMBER 0 0 0 40 N/A 41											
1 9		LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 N/A 43											
2 0		PUBLICITY ISSUED N 44 N/A 45											
7 8 9		NAME OF PREPARER [Signature] PHONE (303) 785-2224 NRC USE ONLY											