



**Commonwealth Edison**

One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

May 2, 1983

50-374

Mr. James G. Keppler, Director  
Directorate of Inspection and  
Enforcement - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Subject: LaSalle County Station, Unit 2  
10CFR50.55(e) Notification 83-01

Dear Mr. Keppler:

Commonwealth Edison filed a 30 day report to your office on March 16, 1983 concerning the status of the problems we experienced with the Riley temperature switches installed in the leak detection system at LaSalle.

In that report it was indicated that the calibration procedure for these devices would be modified to solve the temperature off-set problem. This effort has been completed and presently the switch units have been recalibrated utilizing the revised procedure and are accurately indicating the proper temperature.

At the time of the 30 day report, we anticipated final resolution of the temperature module problem (hardware modification) by the end of April. Presently, General Electric and Riley are still in the process of finalizing the solution. Meetings are planned in San Jose the week of May 2nd to accomplish this task. It is currently anticipated that final resolution will be expected by 6/1/83. A final report will be issued at that time.

If you or your staff have any questions concerning this activity, please contact us at this office.

Very truly yours,

RAB/bmb/2926L

8305100018 830502  
PDR ADDCK 05000374  
S PDR

IE27

MAY 4 1983