

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

May 3, 1983

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/83024

The enclosed report provides details concerning a rod withdrawal error
scenario that conflicted with the plastic strain linear heat generation
rate limit for lead test assembly bundles. This report is submitted in
accordance with Browns Ferry unit 3 Technical Specification 6.7.2.a(8).

Very truly yours,

TENNESSEE VALLEY AUTHORITY



H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

8305100107 830503
PDR ADOCK 05000296
S PDR

An Equal Opportunity Employer

ORIGINAL COPY

IE 22

03 MAY 5 10:00