

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

May 4, 1983

BLRD-50-439/83-25

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


BELLEFONTE NUCLEAR PLANT UNIT 2 - DRAWING DISCREPANCY FOR INCORE MONITOR
TANK SLEEVES - BLRD-50-439/83-25 - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
Linda Watson on April 5, 1983 in accordance with 10 CFR 50.55(e) as
NCR 2317. Enclosed is our first interim report. We expect to
submit our next report by December 22, 1983.

If you have any questions, please get in touch with R. H. Shell at
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Licensing

Enclosure

cc: Mr. Richard C. DeYoung, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center (Enclosure)
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY

8305130089 830504
PDR ADOCK 05000439
S PDR

LE 27

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNIT 2
DRAWING DISCREPANCY FOR INCORE MONITOR TANK SLEEVES
BLRD-50-439/83-25
10 CFR 50.55(e)
NCR 2317
FIRST INTERIM REPORT

Description of Deficiency

The unit 2 Reactor Building Incore Monitor tank sleeves, for incore piping, (El 639.01 Mark 1 and 2 sleeves) are 18'-2-3/4" and 1'-9-1/2" from the center line of the reactor building. On the unit 1 plan view, the dimensions are 18'-2-3/4" and 2'-3-1/2". As a result, the unit 2 sleeves in the incore tank are installed 6" west of their intended location.

Interim Progress

TVA is investigating the possibility of using the tank sleeves in their present configuration.

Babcock and Wilcox (B&W) has been notified of this condition and has been asked to review the "use as is" possibility since it deviates from their acceptance criteria as outlined in their letter E-3782.