



May 5, 1983

Log No. K83-696

File: RR 2 (NP-33-82-24)
(NP-33-81-40)
(NP-32-81-05)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Revision 1 to Licensee Event Reports 81-032 and 81-058 and three copies of Revision 2 to Licensee Event Report 82-020. These reports were revised to correct the code in block 24, NPRD form submitted.

There has been no change to the supplemental information sheets to these reports, therefore, please destroy only your previous copies of the LER form itself (replacing with the attached revised pages), retaining the respective supplemental information sheets.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies LERs 82-020 & 81-032
40 copies LER 81-058

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Tom Peebles
NRC Resident Inspector
Encl: 1 copy

8305130190 830505
PDR ADDCK 05000346
PDR
S

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

MAY 11 1983

1E27