



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

May 9, 1983

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137


Operating License Nos. DPR-58, DPR-74
Docket Nos. 50-315 and 50-316

Dear Mr. Keppler:

This is to confirm a verbal report which was given to Mr. N.E. DuBry of your office at 1517 hours on May 6, 1983. At that time I informed Mr. DuBry that during a data review we discovered that the Chemical Volume Control System Holdup Tanks were not sampled in the 12 hour time period required when the automatic gas analyzer is inoperable (sample was performed approximately 4 - 5 hours late).

As required by Technical Specification 6.9.1.12, a followup report will be submitted within 14 days.

Sincerely,


W.G. Smith, Jr.
Plant Manager

/bab

cc: John E. Dolan
R.S. Hunter
M.P. Alexich
R.F. Kroeger
B. Germano
R.C. Callen
G. Charnoff
E.R. Swanson/N.E. DuBry RO:III
J.M. Hennigan
R.O. Bruggee, EPRI
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

1E22
MAY 11 1983

8305130206 830509
PDR ADOCK 05000315
S PDR