

CP&L

REGION II
ATLANTA, GEORGIA

Carolina Power & Light Company

83 MAY 10 A 9:34

P. O. Box 101, New Hill, N. C. 27562
May 6, 1983

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest (Suite 3100)
Atlanta, Georgia 30303

NRC-68

CAROLINA POWER & LIGHT COMPANY
SHEARON HARRIS NUCLEAR POWER PLANT
1986-90 - 900,000 KW - UNITS 1 & 2
EMERGENCY SERVICE WATER SELF CLEANING STRAINERS,
PURCHASE ORDER NY-435037, ITEM 128

Dear Mr. O'Reilly:

On April 8, 1983, Mr. A. Hardin of the NRC was notified of a potentially reportable item per the provisions of 10CFR50.55(e). The emergency service water strainers from the vendor (R. P. Adams) contained weld deficiencies. We also stated that this item was potentially reportable per the provisions of 10CFR, Part 21; this, however, after further evaluation, is not correct. The item only has the potential of being in violation of 10CFR50.55(e) since the strainers were not accepted through receipt inspection.

At the present time, the vendor is still evaluating the reported deficiencies on the pressure boundary welds and is not expected to be complete with this until the first of June, 1983. For this reason, we would request an extension until June 17, 1983 for submitting a report on the reportability of this item.

Thank you for your consideration in this matter.

Yours very truly,



R. M. Parsons
Project General Manager
Shearon Harris Nuclear Power Plant

RMP/sh

cc: Mr. G. Maxwell (NRC-SHNPP)
Mr. R. Prevatte (NRC-SHNPP)
Mr. V. Stello (NRC)

8305130216 830506
PDR ADDCK 05000400
S PDR

RECEIVED

IE 27