

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

April 21, 1983  
ANPP-23560-RQT/BSK

CORRECTED COPY\*

U. S. Nuclear Regulatory Commission  
Region V  
Creekside Oaks Office Park  
1450 Maria Lane - Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief  
Reactor Projects Branch 1

Subject: Interim Report - DER 83-17  
A 50.55(e) Potentially Reportable Deficiency Relating to  
Fire Protection Switches By ITE Gould Failed To Meet The  
Requirements Of TMI Task 18A  
File: 83-019-026; D.4.33.2


Reference: Telephone Conversation between P. Narbut and R. Tucker on  
March 4, 1983

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the  
referenced telephone conversation. At that time, it was estimated that a  
determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim  
Report is attached. It is now expected that this information will be  
finalized by May 19, 1983, at which time a complete report will be  
submitted.

Very truly yours,



E. E. Van Brunt, Jr.  
APS Vice President  
Nuclear Projects Management  
ANPP Project Director

EEVB/RQT:db

Attachment

cc: See Attached Page 2

\*Paragraph 2, finalized date should read July 19, 1983.

8305130229 830421  
PDR ADOCK 05000528  
S PDR

DESIGNATED ORIGINAL

Certified By D. L. Blair

IE-27