

CONTROL BLOCK:

--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	6	2	7	0	3	3	1	8	3	8	0	5	0	3	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

02 | While in Mode 5, the fire spray system that protects Control Bldg. Cable Riser Elev. |

03 | 30 ft. spuriously activated. LCO 3.7.8.2 Action Statement 'a' was entered. Also |

04 | LCO 3.3.3.7 Action statement 'a' was entered since the associated actuation fire |

05 | detectors were inoperable until the system was reset on April 30, 1983. A continuous |

06 | fire watch was established within one hour. The affected fire spray system remained |

07 | manually operable. Health and safety of the public were not affected. |

0 8		9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE	
0 9		A B		X		X		I N S T R U				E		Z			
7 8		9 10		11 12		12 13		13 18				19 20		20			
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
LER/RO REPORT NUMBER		8 3		0 3 3		0 3		L		0							
21 22		23		24 26		27		28 29		30		31		32			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER			
X		X		Z		Z		0 0 0 0		N		N		A			
18 19		20		21		22		23		24		25		26			
7 8		9 10		11 12		13 14		15 16		17 18		19 20		21 22			

1 0 | A review of the Control Operator logs and discussions with fire watch and maintenance
1 1 | personnel did not identify any apparent cause of actuation. Compensatory measures
1 2 | remained in place until the fire spray system was returned to service. Initial
1 3 | attempts to reset the deluge valve resulted in valve leakage. As corrective action,
1 4 | the proper resetting technique will be provided, in writing, to Operations personnel.

8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 G (28) 0 0 0 (29) NA A (31) Operator Observation

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)

1 7 0 0 0 (37) Z (38) NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PERSONNEL INJURIES NUMBER DESCRIPTION (41)

1 8 0 0 0 (40) NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

1 9 Z (42) NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PUBLICITY ISSUED DESCRIPTION (45)

2 0 N (44) NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

8305160115 830503
PDR ADOCK 05000362
S PDR

NRC USE ONLY

68 69

PHONE

714/492-7700