

SNUPPS

Standardized Nuclear Unit
Power Plant System

5 Choke Cherry Road
Rockville, Maryland 20850
(301) 869-8010

Nicholas A. Petrick
Executive Director

May 13, 1983

SLNRC 83-0027 FILE: 0278
SUBJ: Power Systems Branch
Review of SNIPPS

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Docket Nos. STN 50-482 and STN 50-483
Reference: SLNRC 83-0024, dated May 9, 1983, Power Systems Branch
Review

Dear Mr. Denton:

The above reference transmitted the SNUPPS response to the Safety
Evaluation Report (SER) Confirmatory Issue No. 19 for Callaway Plant
Unit No. 1 and No. B.20 for Wolf Creek Generating Station Unit No. 1.

It should be noted that the results of all tests conducted on the
isolating regulating transformer, together with the redundant cir-
cuit breaker design change described in the above reference, provide
assurance that all faults that could be postulated on the secondary
circuits supplied by the transformer will not adversely affect the
Class 1E bus.

Very truly yours,


Nicholas A. Petrick

JOC/nld

cc: D. T. McPhee
G. L. Koester
D. F. Schnell

KCPL
KGE
UE

J. H. Neisler USNRC/CAL
H. Roberds/W. Schum USNRC/WC

Boo1