



Commonwealth Edison

One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

August 8, 1983

Mr. James G. Keppler,
Director - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: LaSalle County Station Unit 2
10CFR50.55(e) Notification 83-01
Correction to Final Report, Riley
Temperature Indicating Switches
NRC Docket No. 50-374

Reference (a): C.W. Schroeder letter to J.G. Keppler
dated March 16, 1983.

(b): C.W. Schroeder letter to J.G. Keppler
dated May 3, 1983.

(c): C.W. Schroeder letter to J.G. Keppler
dated June 3, 1983.

Dear Mr. Keppler:

The purpose of this letter is to correct a statement made in Reference (c). The Unit 2 Riley temperature switches have not yet been recalibrated to the modified calibration procedure suggested by Riley. Only the Unit 1 temperature switches have been recalibrated at this time.

We will complete the calibration on Unit 2, using the same calibration procedure as Unit 1, prior to fuel load.

If there are any questions in this matter, please contact this office.

Very truly yours,

F. H. Lentine
for

C.W. Schroeder
Nuclear Licensing Administrator

lm

cc: Region III Inspector - LSCS
Director of Enforcement & Inspection

7106N

8308180346 830808
PDR ADOCK 05000374
S PDR

AUG 12 1983

IF27
1/0