

3130-0011
EXPIRES 4-30-82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE (704) 373-7432

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

USNRC REGION II
ATLANTA, GEORGIA

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

August 11, 1983

83 AUG 17 A8:06

TELEPHONE
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 1
Docket No. 50-369
LER/RO-369/83-55

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/83-55. This report concerns T.S. 3.6.2, "Two independent containment spray systems shall be operable with each spray system capable of taking suction from the RWST and transferring suction to the containment sump". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

H.B. Tucker / HBT

Hal B. Tucker

PBN:jfw
Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

OFFICIAL COPY
1522
11