

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE (714) 492-7700

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92072

H. B. RAY
STATION MANAGER

August 12, 1983

RECEIVED
MRC
SCE
1983 AUG 18 AM 11:26
REGION V
TELEPHONE
(714) 402-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. J.B. Martin, Regional Administrator


Dear Sir:

Subject: Docket No. 50-362
30-Day Report
Licensee Event Report No. 83-049
San Onofre Nuclear Generating Station, Unit 3

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) form for an occurrence involving Limiting Condition for Operation (LCO) 3.4.5.2.d associated with identified leakage from the Reactor Coolant System (RCS). Enclosed LER 83-049 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding the above, please contact me.

Sincerely,



Enclosure: LER No. 83-049

11

IE-22
83-323

August 12, 1983

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)
J.P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)