

50-528  
RECEIVED  
NRC  
1983 AUG 10 PM 1:01  
REGION V  
August 1, 1983  
ANPP-27471-BSK/RQT

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

August 1, 1983  
ANPP-27471-BSK/RQT

U. S. Nuclear Regulatory Commission  
Region V  
Creekside Oaks Office Park  
1450 Maria Lane - Suite 210  
Walnut Creek, CA 94596-5368

Attention: Mr. D. M. Sternberg, Chief  
Reactor Projects Branch 1

Subject: Interim Report - DER 83-39  
A 50.55(e) Potentially Reportable Deficiency Relating to  
Rejectable Indications on CE Supplied Unit 1 Reactor Coolant  
Pump 1A.  
File: 83-019-026; D.4.33.2

Reference: Telephone Conversation between A. D'Angelo and R. Tucker on  
July 1, 1983.

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the  
referenced telephone conversation. At that time, it was estimated that a  
determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim  
Report is attached. It is now expected that this information will be  
finalized by October 27, 1983, at which time a complete report will be  
submitted.

Very truly yours,

E. E. Van Brunt

E. E. Van Brunt, Jr.  
APS Vice President,  
Nuclear Projects Management  
ANPP Project Director

EEVBJr./RQT:rb  
Enclosure

cc: See Page Two

8308220198 830801  
PDR ADOCK 05000528  
S PDR

11 JE27

U. S. Nuclear Regulatory Commission  
Page Two

cc: Richard DeYoung, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

T. G. Woods, Jr.  
G. C. Andognini  
J. A. Roedel  
D. B. Fasnacht  
A. C. Rogers  
B. S. Kaplan  
W. E. Ide  
J. Vorees  
J. R. Bynum  
P. P. Klute/D. D. Green  
A. C. Gehr  
W. J. Stubblefield  
W. G. Bingham  
R. L. Patterson  
R. W. Welcher  
R. M. Grant  
D. R. Hawkinson  
L. E. Vorderbrueggen  
G. A. Fiorelli  
S. R. Frost  
J. Self

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway - Suite 1500  
Atlanta, Georgia 30339

8/1/83

INTERIM REPORT - DER 83-39  
POTENTIAL REPORTABLE DEFICIENCY  
ARIZONA PUBLIC SERVICE COMPANY (APS)  
PVNGS UNIT 1

I. POTENTIAL PROBLEM

On a recent re-examination and comparison between the Preservice Examination Ultrasonic (UT) data and the construction Radiographs (RT) for the Combustion Engineering (C-E) furnished Reactor Coolant Pump 1A/IMRCEPOIA, two linear indications were found. The indications exist in the circumferential weld of the pump casing.

One of the RT indications found measures 3 inches long; the second measures 3/4 inches long. Both exist within a length of 6 inches. Subsequent examinations have shown that these indications are approximately 3.2 inches in from the outside diameter of the casing with no perceptible through wall dimension. The base metal of the casing in this area is 5-5/8 inches thick. The linear indications are acceptable to the ASME Section III UT acceptance criteria but do not meet the ASME Section III RT acceptance criteria. A Fracture Mechanics Analysis has been performed by C-E on the casing using conservative parameters. The analysis assumed: (1) the indications have a through wall dimension of 3/4 inches; and (2) the indication is a sharp crack extending around the entire circumference of the casing.

II. APPROACH TO AND STATUS OF PROPOSED RESOLUTION

Bechtel is continuing to correspond with CE on this matter to determine reportability.

III. PROJECTED COMPLETION OF CORRECTIVE ACTION AND SUBMITTAL OF THE FINAL REPORT

Evaluation of this condition and submittal of the Final Report is forecast to be completed by October 27, 1983.