




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

August 11, 1983
REG- 15,651
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011





Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-103

On March 25, 1983, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning linear indications found in the lifting lugs on the containment dome (DR-103). GSU has not completed its evaluation. An interim or final status report will be provided by October 13, 1983.

Sincerely,


for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group


JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)

8308220201 830811
PDR ADOCK 05000458
S PDR

1E-27

40