



Consumers
Power
Company

James W Cook

Vice President - Projects, Engineering
and Construction

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-2453

August 2, 1983

Mr J G Keppler, Regional Administrator
US Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

MIDLAND ENERGY CENTER GWO 7020
INSPECTION REPORT NO 50-329/83-10(OSC) AND 50-330/83-10(OSC)
File: 0.4.2 UFI: 70*01 Serial: CSC-6807
0485.16 42*05*22*04

REFERENCE: (1) R F Warnick letter to J W Cook, dated June 30, 1983
Inspection Report No 50-329/83-10(OSC) and 50-330/83-10(OSC)

This letter, including Attachment 1, provides our response to Reference 1, which transmitted the subject Inspection Report and which requested our written response to the item of noncompliance therein. Based on a telecon with R F Warnick of Region III on July 29, CPCo was given an extension on the response due date.

James W. Cook

JWC/BHP/dmh

Attachment

cc: RFWarnick, NRC Region III
JJHarrison, NRC Region III
RNGardner, NRC Region III
RBLandsman, MPC Region III
RJCook, NRC Senior Resident Inspector, Midland Site
RLBurgess, NRC Resident Inspector, Midland Site

8308220293 830817
PDR ADOCK 05000329
Q PDR

NOV0783-0002-CN02

AUG 08 1983


CONSUMERS POWER COMPANY
Midland Units 1 and 2
Docket No 50-329/50-330

Letter Serial CSC-6807 Dated August 2, 1983


At the request of the Commission and pursuant to the Atomic Energy Act of 1954, and the Energy Reorganization Act of 1974, as amended and the Commission's Rules and Regulations thereunder, Consumers Power Company submits the response to J G Keppler letter to J W Cook dated June 30, 1983.

CONSUMERS POWER COMPANY

By


J W Cook, Vice President
Projects, Engineering and Construction

Sworn and subscribed before me this 2nd day of August, 1983.


Beverly A. Avery

Notary Public

Jackson County
Michigan

My Commission Expires

January 16, 1985

OL/OM SERVICE LIST

Mr Charles Bechhoefer, Esq
Administrative Judge
Atomic Safety & Licensing Board Panel
US Nuclear Regulatory Commission
Washington, DC 20555

Dr Frederick P Cowan
Administrative Judge
6152 N Verde Trail
Apt B-125
Boca Raton, FL 33433

Mr Michael Miller, Esq
Isham, Lincoln & Beale
3 First National Plaza
Suite 5200
Chicago, IL 60602

Mr D F Judd, Sr Project Manager
The Babcock & Wilcox Company
P O Box 1260
Lynchburg, Va 24505

Atomic Safety & Licensing Board Panel
U S Nuclear Regulatory Commission
Washington, DC 20555

Atomic Safety & Licensing Appeal Board
U S Nuclear Regulatory Commission
Washington, DC 20555

Mr William D Paton, Esq
Counsel for NRC Staff
US Nuclear Regulatory Commission
Washington, DC 20555

Ms Barbara Stamiris
5795 North River Road
Route 3
Freeland, MI 48623

Dr Jerry Harbour
US Nuclear Regulatory Commission
Atomic Safety & Licensing Board Panel
Washington, DC 20555

Mr Frank J Kelley, Esq
Attorney General of the
State of Michigan
Mr Stewart H Freeman, Esq
Assistant Attorney General
Environmental Protection Div
720 Law Building
Lansing, MI 48913

Mr Myron M Cherry, Esq
Cherry & Flynn
3 First National Plaza
Suite 3700
Chicago, IL 60602

Mr Wendell H Marshall
RFD 10
Midland, MI 48640

Mr John DeMeester
Dow Chemical Building
Michigan Division
Midland, MI 48640

Ms Mary Sinclair
5711 Summerset Street
Midland, MI 48640

Mr Steve Gadler
2120 Carter Avenue
St Paul, MN 55108

Mr Lee L Bishop
Harmon & Weiss
1725 I Street, NW #506
Washington, DC 20006

Mr C R Stephens
Docketing and Service Station
Office of the Secretary
US Nuclear Regulatory
Washington, DC 20555

Lynn Bernabei
Governmental Accountability
Project (GAP)
1901 Q Street NW
Washington, DC 20009

Attachment 1
Serial: CSC-6807

CONSUMERS POWER COMPANY'S RESPONSE TO
US NUCLEAR REGULATORY COMMISSIONER, REGION III
INSPECTION REPORT NO 50-329/83-10 (OSC) & 50-330/83-10 (OSC)

Appendix (Notice of Violation) to Inspection Report No 50-329/83-10 (OSC) and 50-330/83-10 (OSC) provides an item of noncompliance to 10 CFR 50, Appendix B. The NRC statement and our response are given below:

NRC STATEMENT

"10 CFR 50, Appendix B, Criterion XV states, in part, "Measures shall be established to control materials, parts, or components which do not conform to requirements in order to prevent their inadvertent use or installation. These measures shall include, as appropriate, procedures for identification, documentation, segregation, disposition and notification to affected organizations."

Contrary to the above, the licensee did not have measures to control heating, ventilation and air conditioning (HVAC) components stored in the Poseyville Road laydown areas which would prevent the inadvertent use of nonconforming items. Procedures did not exist which required identification, documentation and segregation for HVAC items of questionable quality stored in proximity to acceptable safety related items at the laydown area.

This is a Severity Level IV violation (Supplement II).

CONSUMERS POWER COMPANY RESPONSE

In accordance with this Notice of Violation, an explanation of corrective action is as follows:

1) Corrective Action Taken and Results Achieved

The Zack Company reorganized the Poseyville Road laydown area to segregate items of questionable quality as identified in the Notice of Violation. Coincident with the NRC inspection of the laydown area, the Zack Company issued for implementation on April 29, 1983, MB-FP-21 Revision 0, "The Zack Company Midland Project Procedure for Removal/Reinstallation/Restocking." A segregated restocking storage area has been assigned and components or materials are properly identified and handled per the above procedure. The procedure further requires BPCo signature approval for the withdrawal of materials from the restocking area (to maintain commercial accountability and to control scrapping) and the procedure specifically prohibits re-use of restocked ducts or hangers in Q applications.

The Zack Company has additionally initiated more frequent and routine surveillance and maintenance of the area in accordance with the already existing MB-FP-2, Rev 2, Storage and Maintenance procedure and Bechtel Specification M-151A Section 4 requirements.

2) Corrective Action to be Taken to Avoid Further Noncompliance

MB-FP-2 Rev 2 "Storage and Maintenance" and MB-FP-21 Rev 0 "Removal Reinspection/Restocking" will be revised further to support item 1 above. Written instructions will be developed to incorporate requirements of MB-FP-2, MB-FP-21 and Specification M-151 A.

3) Date When Full Compliance will be Achieved

Corrective action is complete for the specific item of noncompliance. Written instructions will be completed by September 1, 1983.