

yellow

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

July 29, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Re: RII:JPO
Catawba Nuclear Station
Docket Nos. 50-413 and 50-414


Dear Mr. O'Reilly:

In response to Mr. Richard C. DeYoung's letter of May 13, 1983, which transmitted IE Bulletin 83-05, please be advised that a review for the Catawba Nuclear Station has been conducted. There are no Hayward Tyler Pump Company pumps or spare parts at Catawba.

This review required approximately 10 man-hours to complete and report.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge.

Very truly yours,



Hal B. Tucker

RWO/php

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Resident Inspector
Catawba Nuclear Station

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

Palmetto Alliance
2135½ Devine Street
Columbia, South Carolina 29205

8308230238 830729
PDR ADOCK 05000413
Q PDR

83 AUG 4 AIO: 00
USNRC REGION II
ATLANTA, GEORGIA

1/0 IE11