

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

026-716 045

NARRATIVE REPORT
FOR LER 50-366/1983-024

LICENSEE : GEORGIA POWER COMPANY
FACILITY NAME : EDWIN I. HATCH
DOCKET NUMBER : 50-366

Tech. Specs. section(s) which requires report:

This 30-day LER is required by Tech. Specs. section 6.9.1.9.b., due to the event's showing that the unit was not meeting the requirements of Tech. Specs. section 3.3.6.4-1.

Plant conditions at the time of the event(s):

On April 11, 1983, the plant was in Refuel.

Detailed description of the event(s):

During performance of "PRIMARY CONTAINMENT TEMPERATURE" surveillance calibration procedure (HNP-2-3879), plant personnel noted that alarm point number 1 alarmed at 220°F (expected alarm point of 95°F), alarm point number 2 alarmed at 195°F (expected alarm point of 120°F), and alarm point number 3 alarmed at 225°F (expected alarm point of 148°F). These incorrect alarm setpoints caused the instrument to be declared inoperable.

Consequences of the event(s):

There were no consequences of this event with plant in refuel mode. The health and safety of the public were not affected by this event.

Status of redundant or backup subsystems and/or systems:

The redundant primary containment temperature recorder (2T47-R626) was operable.

Justification for continued operation:

2T47-R627 is not required to be operable when the unit is in refuel.

If repetitive, number of previous LER:

This is a non-repetitive event.

Impact to other systems and/or Unit:

This problem does not affect other plant systems, nor does it affect unit one.

Cause(s) of the event(s):

The cause of this event was attributed to setpoint drift.

Narrative Report for LER 50-366/1983-024
Page Two

Immediate Corrective Action:

The alarm setpoints for 2T47-R627 were recalibrated per HNP-2-3879. 2T47-R627 was returned to service on April 11, 1983.

Supplemental Corrective Action:

No supplemental corrective action is required.

Scheduled (future) corrective action:

No scheduled future corrective action is required.

Action to prevent recurrence (if different from corrective actions):

No further action is required to prevent recurrence.