

Charles W. Jackson
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Ave.,
Buchanan, NY 10511
Telephone (914) 737-8116

Date: August 1, 1983

Re: Indian Point Unit No. 2
Docket No. 50-247

Dr. Thomas E. Murley, Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Dr. Murley:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following confirms notification on July 29, 1983 to Mr. Thomas Kenny of your office, by Mr. John Basile and Mr. Michael Blatt of Consolidated Edison of a potential Reportable Occurrence. This event is the type defined in Technical Specification, Section 6.9.1.7.


Con Edison has been conducting a program to review and upgrade its operating procedures and checkoff lists. On July 29, 1983 as a result of plant staff review of non-licensed operator log sheets we determined that the identification of the operating status of the Isolation Valve Seal Water System tank did not adequately correspond to the requirements of Technical Specification 3.3C.1.b. Our review back through 1982, however, indicates that when the unit was in power operation, the equivalent pressure, including the effective elevation head, assured that the Technical Specification 52 psig was available at the delivery point to the isolation valves.

Immediate corrective action was taken to assure that the locally indicated pressure on the tank is maintained consistent with the Technical Specification without taking credit for the elevation head. In addition, the schedule for the ongoing procedure review program was revised to expedite review, and revise as necessary, the non-licensed operator log sheets. This revised review schedule was implemented July 29, 1983 and is expected to be completed approximately August 5, 1983.

Additional information associated with this review of non-licensed operator logs will be provided in a supplemental report.

Con Edison believes that this report also satisfies the requirements of 10 CFR Part 21.

Very truly yours,



CWJ:ah
cc: List Attached

8308310095 830801
PDR ADOCK 05000247
S PDR

IE22
1/0

cc: Mr. William McDonald, Director (2 copies)
Office of Management Information and
Program Control
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. T. Foley, Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

Mr. T. Kenny, Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 66
Buchanan, New York 10511