

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

USNRC REGION II
ATLANTA, GEORGIA
TELEPHONE
(704) 373-4531

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

August 24, 1983

83 AUG 29 49:30

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 1
Docket No. 50-369
LER/RO-369/83-65

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/83-65 was to have been submitted by August 24, 1983. This 30-day reportable occurrence (per T.S. 6.9.1.11) concerns T.S. 3.4.3, "The pressurizer shall be operable with . . . at least two groups of pressurizer heaters each having a capacity of at least 150 kw." which was violated on July 25, 1983. The information required for this report is not yet available. Submittal of the complete report is expected by August 31, 1983.

Very truly yours,

Hal B Tucker by WAH
Hal B. Tucker

REH/ibh

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

8309060155 830824
PDR ADCCK 05000369
S PDR

IE 22
110