

3150-0011
E-X-1000 4-30-82

PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

8309150266 830831
PDR ADOCK 05000370
S PDR

IF22

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

August 31, 1983

USNRC REGION II
ATLANTA, GEORGIA
TELEPHONE
(704) 373-4531
83 SEP 12 48:19


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street NW, Suite 2900
Atlanta, Georgia 30303

Subject: McGuire Nuclear Station Unit 2
Docket No. 50-370
LER/RO-370/83-37

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-370/83-37. This report concerns T.S. 3.3.3.7, "As a minimum, the Fire Detection Instrumentation for each Fire Detection Zone shown in Table 3.3-11 shall be operable". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

PBN:jfw
Attachment

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

OFFICIAL COPY

IE 22 11