




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

July 8, 1983
RBG-15,413
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-93

In our Interim Report dated May 25, 1983, Gulf States Utilities Company (GSU) informed Region IV of the status of the condition potentially reportable under 10CFR50.55(e) concerning documentation and code stamping of the interconnecting piping between the Reactor Water Cleanup heat exchangers (DR-93). GSU is awaiting information from the supplier of the interconnecting piping (Atlas Industrial Manufacturing Company). An interim or final status report will be submitted by August 12, 1983.

Sincerely,

J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JRD
JEB/PJD/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)

8307190179 830708
PDR AD0CK 05000458
S PDR

IE-27
40