



**CENTERIOR
ENERGY**

6200 Oak Tree Boulevard
Independence OH
216-447-3100

Mail Address
P.O. Box 94661
Cleveland, OH 44101-4661

Docket Number 50-346

License Number NPF-3

Serial Number 2257

October 31, 1994

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Technical Specification 4.4.5.5a Report of Steam Generator
Tube Plugging

Gentlemen:

This letter is submitted in accordance with the requirements of the Davis-Besse Nuclear Power Station (DBNPS) Unit Number 1, Operating License, Appendix A, Technical Specifications. Technical Specification 4.4.5.5a requires Toledo Edison to report to the Nuclear Regulatory Commission (NRC) the number of tubes plugged in each steam generator (SG) following each inservice inspection of steam generator tubes.

The Ninth Refueling Outage SG tube inservice inspection was completed on October 17, 1994. As a result of the inspection findings, 2 tubes were plugged in SG 1-1 and 1 tube was plugged in SG 1-2. In addition, preventive sleeving was installed in 199 tubes in SG 1-2.

Toledo Edison will provide the complete results of the steam generator tube inservice inspection in accordance with Technical Specifications 4.4.5.5b and 6.9.1.5b. This report will include: 1) the number and extent of tubes inspected, 2) the location and percent of wall-thickness penetration for each indication of an imperfection, and 3) the identification of tubes plugged or sleeved. This report is submitted on an annual basis and is due March 31, 1995.

9411090128 941031
PDR ADOCK 05000346
Q PDR


Operating Companies
Cleveland Electric Illuminating
Toledo Edison

A047
1/0

Docket Number 50-346
License Number NPF-3
Serial Number 2257
Page 2

Should further information be required, please contact
Mr. W. T. O'Connor, Manager - Nuclear Licensing, at (419) 249-2366.

Very truly yours,

A handwritten signature in dark ink, appearing to read "J. B. Martin". The signature is fluid and cursive, with the first name "J. B." and the last name "Martin" clearly distinguishable.

FWK/laj

cc: L. L. Gundrum, DB-1 NRC/NRR Project Manager
J. B. Martin, Regional Administrator, NRC Region III
S. Stasek, DB-1 NRC Senior Resident Inspector
Utility Radiological Safety Board