



## Duquesne Light

Nuclear Construction Division  
Robinson Plaza, Building 2, Suite 217  
Pittsburgh, PA 15205

2NRC-3-040

(412) 787-3141

(412) 923-1960

Teletype (412) 787-2629

July 6, 1983

United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA 19406

ATTENTION: Dr. T. E. Murley  
Administrator

SUBJECT: Beaver Valley Power Station - Unit No. 2  
Docket No. 50-412  
Quality Control Acceptance of Conditions Not Conforming to Inspection Plan Attributes  
Significant Deficiency Report No. 83-02

REFERENCES: (a) 2NRC-3-014, dated March 18, 1983  
(b) 2NRC-3-023, dated April 29, 1983

Gentlemen:

This interim report is in response to the significant deficiency regarding Beaver Valley Power Station, Unit No. 2 (BVPS-2) Quality Control program previously discussed in References (a) and (b). In these references, Duquesne Light Company (DLC) provides a description and evaluation of the deficiency and the corrective action taken. DLC has determined that this deficiency meets the criteria stated within 10CFR50.55(e)(1)(i) as a significant breakdown in a portion of the quality assurance program.

Previously, DLC stated that results of an additional engineering evaluation to establish the safety significance of the subject inspection errors will also be reported. However, it is needless to do a further engineering evaluation on this item to determine if 10CFR50.55(e)(1)(iii) or (iv) is also applicable since only one criteria in 10CFR50.55(e)(1) is sufficient cause for reporting. Items found unsatisfactory from the reinspection program previously described for Significant Deficiency 83-02 will be handled by the normal process, which includes screening items for potential 10CFR50.55(e) criteria. Any unsatisfactory item found during the reinspection program which meets 10CFR50.55(e) criteria will result in a new reportable significant deficiency.

These ideas have been discussed with the BVPS-2 resident NRC inspector, and he concurs that this approach is acceptable. Therefore, BVPS-2 Quality Control will complete the reinspection program for Significant Deficiency 83-02 with any unsatisfactory items being handled through normal established procedures. DLC will periodically issue the results of the continuing reinspection.

program to the NRC until final completion. Significant Deficiency 83-02 will be considered closed by DLC when the 100% reinspection program previously described in References (a) and (b) is completed.

DUQUESNE LIGHT COMPANY

By E. J. Woolever  
E. J. Woolever  
Vice President

RWF/wjs

cc: Mr. R. DeYoung, Director, Office of Inspection & Enforcement (3)  
Mr. G. Walton, NRC Resident Inspector  
Ms. L. Lazo, Project Manager  
NRC Document Control Desk  
INPC Records Center

COMMONWEALTH OF PENNSYLVANIA )  
 ) SS:  
COUNTY OF ALLEGHENY )

On this 6th day of July, 1983, before me, a Notary Public in and for said Commonwealth and County, personally appeared E. J. Woolever, who being duly sworn, deposed and said that (1) he is Vice President of Duquesne Light, (2) he is duly authorized to execute and file the foregoing Submittal on behalf of said Company, and (3) the statements set forth in the Submittal are true and correct to the best of his knowledge.

Anita Elaine Reiter  
Notary Public

ANITA ELAINE REITER, NOTARY PUBLIC  
ROBINSON TOWNSHIP, ALLEGHENY COUNTY  
MY COMMISSION EXPIRES OCTOBER 20, 1986