

USNRC REGION II  
**DUKE POWER COMPANY**  
P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

83 JUL 15 P 1: 53

TELEPHONE  
(704) 373-4531

July 8, 1983

Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street NW, Suite 2900  
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 2  
Docket No. 50-370

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-370/83-27 was to have been submitted by July 8, 1983. This 30 day reportable occurrence (per T.S. 6.9.1.11) concerns T.S. 3.6.3, "The containment isolation valves specified in Table 3.6-2 shall be operable with isolation times as shown in Table 3.6-2," which was violated on June 9, 1983. At this time investigation of the incident and preparation of a report are not yet complete. The report will be submitted by July 22, 1983.

Very truly yours,

*H.B. Tucker / BT*

Hal B. Tucker

PBN:jfw

cc: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. W. T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

OFFICIAL COPY

*IE 22*

*1/0*

8307220499 830708  
PDR ADOCK 05000370  
S PDR