



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 13, 1983

W3I83-0234

Q-3-A35.07.76

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 76
"Damage to Pressurizer Heaters During
Hot Functional Testing"
Second Interim Report

REFERENCE: LP&L letter W3I83-0119 dated April 25, 1983

Dear Mr. Collins:

The above referenced letter indicated that further information would be submitted to the USNRC by July 15, 1983.

At the present time, all thirty (30) of the pressurizer heaters are scheduled to be replaced. Installation of the heaters will be performed by Plant Staff Maintenance personnel. Welding associated with the installation will be in accordance with ASME Section XI. Completion of the work is estimated for August 15, 1983.

A Final Report will therefore be submitted to the USNRC by September 15, 1983.

Very truly yours,

Thomas F. Drummond for

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8307260356 830713
PDR ADOCK 05000382
S PDR

1/0
IE-27