

USNRC REGION II
ATLANTA, GEORGIA
HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTS
83 JUL 22 AIO: 07

DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 28242

TELEPHONE
(704) 373-4531

July 12, 1983


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Re: Catawba Nuclear Station
Units 1 and 2
Docket Nos. 50-413 and 50-414

Dear Mr. O'Reilly:

In the Corrective Action section of Significant Deficiency Report SD 413-414/81-25, dated November 13, 1981, it was stated that the SAL relay modification kits were to be ordered and installed by January 1, 1983; instead, the SAL relays were returned to Westinghouse for repair. This caused a delay in expected installation date. The relays have been returned to Duke and are to be installed by August 1, 1983.

Very truly yours,



Hal B. Tucker

RWO/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector
Catawba Nuclear Station

Palmetto Alliance
2135 1/2 Devine Street
Columbia, South Carolina 29205

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. Robert Guild, Esq,
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

8307260426 830712
PDR ADCK 05000413
S PDR

OFFICIAL COPY

IE 22
110