

USNRC REGION II
ATLANTA, GEORGIA

CP&L

Carolina Power & Light Company

83 JUL 22 AID: 07 Box 101, New Hill, North Carolina 27562
July 15, 1983

FILE: SH N-2/18
Item 121

MQAH 83-177

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1
DOCKET NO. 50-400

WELDING DEFICIENCIES IN THE MAIN STEAM/FEEDWATER SUPPORT FRAMES

Dear Mr. O'Reilly:

This is to confirm the July 15, 1983 telephone conversation between Mr. N. J. Chiangi and Mr. A. Hardin. Mr. Hardin was informed that the March 18, 1983 potentially reportable item, pertaining to two Main Steam/Feedwater Support Frames (Nos. C-1-189 and C-1-195) that were received and accepted from PX Engineering and were placed on hold due to information received from Ebasco (on March 17, 1983) that Frame No. C-1-188 scheduled for SHNPP had welds that were "slugged", has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e) and 10CFR Part 21.

Thank you for your consideration in this matter.

Yours very truly,

NJC/mt

cc: Mr. R. C. DeYoung
Mr. G. Maxwell
Mr. R. L. Prevatte

N. J. Chiangi
N. J. Chiangi - Manager
Quality Assurance/Quality Control
Harris Plant

8307260485 830715
PDR ADOCK 05000400
S PDR

OFFICIAL COPY
IE 27
110