



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
NEW ORLEANS, LOUISIANA

• P.O. BOX 6008
70174-6008

• (504) 366-2345

July 21, 1983

W3P83-1220
Q-3-A29.20

Director of Nuclear Reactor Regulation
Attention: Mr. G. W. Knighton, Chief
Licensing Branch Number 3
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

SUBJECT: Waterford 3 SES
Docket Number 50-382
SER Issues - License Event Report Procedures

Dear Sir:

As part of our effort in closing-out SER issues, we have identified the following issue which we believe has been resolved, yet has not been closed-out in the SER:

LER on Megawatt Demand Setter or Reactor Power Cutback malfunctions
(License Condition) - The required procedure (UNT-6-002) has been revised to require an LER on the noted malfunctions.

It is our understanding that the implementation of this procedure will satisfy the NRC's concerns, and as such we request that an SER supplement be written to remove this License Condition.

If you have any questions regarding this matter, please feel free to contact Roy Prados at (504) 363-8773.

Yours very truly,

F. J. Drummond
Project Support Manager-Nuclear

FJD/RMF/ssd

cc: E. L. Blake, W. M. Stevenson, J. Wilson (NRC), L. Constable

3001
1/0