

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 0 4 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 19 LICENSE NUMBER 25 28 LICENSE TYPE 30 37 CAT 38

0 1 REPORT SOURCE L 0 5 0 0 0 3 1 6 0 7 10 4 8 3 0 7 1 8 8 3 9  
7 8 9 DOCKET NUMBER 52 59 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 WHILE ON TOUR OF CONTAINMENT, A REACTOR OPERATOR FOUND WATER COMING FROM DRAIN LINE  
0 3 ON HV-CFT-2, CONTAINMENT AUX. CHARCOAL FILTER FAN #2. IT WAS DETERMINED TO BE  
0 4 VALVE ZRV-13 (NESW FIRE PROTECTION VALVE) LEAKING BY. THE MANUAL ISOLATION VALVE  
0 5 IFP-307, FOR ZRV-13, WAS ALSO FOUND WITH A PACKING LEAK. PUBLIC HEALTH AND SAFETY  
0 6 WERE NOT AFFECTED. THIS REPORT IS BEING MADE IN ACCORDANCE WITH THE REQUIREMENTS  
0 7 OF IE BULLETIN NO. 80-24. PREVIOUS OCCURRENCES OF THIS TYPE WERE 315-81-020 AND  
0 8 316-81-028.

0 3 SYSTEM CODE A B 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V E X 14 COMP SUBCODE X 15 VALVE SUBCODE E 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER/RO REPORT NUMBER 8 3 21 22 23 SEQUENTIAL REPORT NO. 0 5 5 24 25 26 27 OCCURRENCE CODE 0 1 28 29 REPORT TYPE T 30 31 REVISION NO. 0 32  
ACTION TAKEN E 18 Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 37 40 ATTACHMENT SUBMITTED N 22 NRC-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER H 0 3 5 25  
32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 1 ZRV-13 (A 3-WAY VALVE) WAS CYCLED TWICE TO REMOVE THE SAND FROM THE VALVE WHICH  
1 2 PREVENTED PROPER SEATING OF THIS VALVE. MANUAL ISOLATION IFP-307, FOR ZRV-13,  
1 3 PACKING WAS ADJUSTED TO CORRECT THIS LEAK.

1 5 FACILITY STATUS G 28 % POWER 0 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION OPERATOR OBSERVATION 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 6 ACTIVITY CONTENT Z 33 Z 34 NA 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE NA 37  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
2 0 PUBLICITY N 44 DESCRIPTION NA 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8308040190 830718  
PDR ADOCK 05000316  
S PDR

NRC USE ONLY

NAME OF PREPARER D. R. ROBINSON

PHONE: 616-465-5901



**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

July 18, 1983

Mr. J.G. Keppler, Regional Administrator  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137


Operating License: DPR-74  
Docket No.: 50-316

Dear Mr. Keppler:

This report, LER 83-055, is being submitted in accordance with the requirements of IE Bulletin 80-24 entitled Prevention of Damage Due To Water Leakage Inside Containment. During the course of investigating this event the question of whether this condition was reportable was raised. We previously had raised the question of reportability when we transmitted Licensee Event Report 81-028 on July 20, 1983, which was responded to by your office on August 20, 1981. In this response a statement was made that "We intend to discuss the subject of NRC reporting requirements during future meetings with you and other representatives of the Indiana and Michigan Electric Company".

If at all possible I would like to pursue the outcome of these meetings with you in an effort to establish the criteria for reporting leaks of this type.

Sincerely,

  
W.G. Smith, Jr.  
Plant Manager

/jas

cc: J.E. Dolan  
M.P. Alexich  
R.F. Kroeger  
B. German  
E.R. Swanson/N.E. DuBry, RO:III  
R.C. Callen, MPSC  
G. Charnoff, Esq.  
J.M. Hennigan

R.G. Bruggee, EPRI  
INFO  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (40 copies)  
Dir., MIPC (4 copies)

JUL 20 1983

IE 22 1/1