



NIAGARA MOHAWK POWER CORPORATION / 300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202 / TELEPHONE (315) 474-1511

July 21, 1983  
(7078)

Mr. R. W. Starostecki, Director  
U.S. Nuclear Regulatory Commission  
Region I  
Division of Project and Resident Programs  
631 Park Avenue  
King of Prussia, PA 19406

Re: Nine Mile Point Unit 2  
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is a 30-day interim report in accordance with 10CFR50.55(e) for the problem concerning uncertified field quality control (FQC) inspectors. This condition was reported via telecon to Mr. H. Kister of your staff on June 20, 1983.

Very truly yours,

D. P. Dise  
Vice President  
Quality Assurance

DPD/TL:ja  
Enclosure

xc: Director of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. R. Gramm, Resident Inspector

NIAGARA MOHAWK POWER CORPORATION  
NINE MILE POINT UNIT 2  
DOCKET NO. 50-410

Interim Report for a Problem  
Concerning Uncertified Field  
Quality Control Inspectors

Description of the Problem

The problem pertains to inspections performed by six Stone & Webster Field Quality Control inspectors. The inspectors and activities in question are as follows:

1. Three inspectors in preventative maintenance
2. One inspector in welding
3. One inspector in concrete curing
4. One inspector in drilled-in anchors

This problem is under investigation. A final report will be submitted by August 19, 1983.