

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE 617-746-7900

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

July 27 , 1983

BECO Ltr. #83-197

Regional Administrator, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406


Docket Number 50-293
License DPR-35

Dear Sir:

The attached Licensee Event Report 83-039/03L-0, "HPCI Hydraulic Control Orifice Plate Gasket", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.2.b.

If there are any questions on this subject, please contact us.

Respectfully submitted,


William D. Harrington

WDH:em

Enclosure: LER 83-039/03L-0

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECO LER Distribution

IE22
11