




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 29, 1983

W3I83-0254
Q-3-A35.07.57

Mr. John T. Collins, Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 57
"Inadequate Instrumentation & Control
Installations & Turnover Documentation"
Fifth Interim Report


REFERENCE: LP&L letter W3I83-0229 dated July 5, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than July 29, 1983.

The supporting documentation for this deficiency is presently under review. This review is scheduled for completion in September, 1983 and a Final Report will therefore be submitted to the USNRC by October 14, 1983.

Very truly yours,


F. J. Drummond
Project Support Manager - Nuclear

FJD/WAC/DEB:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8308160091 830729
PDR ADOCK 05000382
S PDR

IE-27
1/0