

50-322 OL

HUNTON & WILLIAMS

707 EAST MAIN STREET P. O. Box 1535

RICHMOND, VIRGINIA 23212

TELEPHONE 804 - 788 - 8200

August 12, 1983

DOCKETED
USNRC

'83 AUG 11 1983
1918 BENNETT AVENUE, N. W.
P. O. BOX 19250
WASHINGTON, D. C. 20036
202-223-8650

OFFICE OF SECRETARY
DOCKETING & SERVICE
FILE NO. 24566.3
BRANCH

DIRECT DIAL NO. 804 788- 8357

BY HAND

Lawrence Brenner, Esq.
Administrative Judge
Atomic Safety and Licensing
Board Panel
U.S. Nuclear Regulatory
Commission
Washington, D.C. 20555

Dr. George A. Ferguson
Administrative Judge
Atomic Safety and Licensing
Board Panel
U.S. Nuclear Regulatory
Commission
Washington, D.C. 20555

Dr. Peter A. Morris
Administrative Judge
Atomic Safety and Licensing
Board Panel
U.S. Nuclear Regulatory
Commission
Washington, D.C. 20555

Electrical Separation

Gentlemen:

Enclosed, pursuant to the "Resolution of SC Contention 31/SOC Contention 19(g) -- Electrical Separation," as amended, is "LILCO's Report Documenting Implementation Of The Electrical Separation Agreement." As the Report indicates in more detail, the two basic results of the inspection conducted in accordance with the agreement are: (1) the number of violations detected, 5, was below the threshold, 9, which would trigger a 100% inspection; and (2) LILCO has not used "Redesco Option 4" (analysis) to resolve any violations or in-process deviations, and therefore no


8308160458 830812
PDR ADOCK 05000322
PDR
Q

DS03

HUNTON & WILLIAMS

matters arising from the inspection are available for litigation. The two other principal matters covered by the agreement, but not involving the inspection, namely the RPS reactor generator sets and the NSSS cabinets, had been closed out earlier.

Respectfully submitted,



Donald P. Irwin
One of Counsel to Long
Island Lighting Company

91/730

Enclosures

cc w/enclosures: Attached Service List