

(From Typed Stages Data.)

Question 19.

Based on the attached computer printout the following pts were printed:

Time	MPX	Temp
05:21:08	402	283.0
05:21:16	403	211.3 = paper rolled down
05:21:26	404	218.6
05:21:35	404	218.6

With the paper rolled down such that (3) MPX points appear together its possible that the operator assumed the points group together to be 402, 403, 404 (also assume he didn't read the MPX pts or pt. title). It should be noted that 403 is not a keying error since this corresponds to a rolled reading:

Actual MPX Pt

403

404

404

Possible Reading Error MPX Pt

402

403

404

B+W EXH:0:T 551

8307080738